Kernel Fails To Reconfigure On IRIX 6.5.30

Published 09/21/2012

Fact(s):

SGI Origin 200
SGI Origin 2000
Kernel update
kernel

SGI Solution:

Remove L1 statement in /var/sysgen/system/irix.sm file due to Origin 2000 Platform does not have an L1. Then, perform autoconfig again.

Answers others found helpful

- 7241 - XLV fixes for IRIX 6.5.30
- Applications are slower since IRIX upgrade to Irix 6.5.30
- 7233 - networking updates for 6.5.30

Additional Details

Creation Date	08/23/2012 08:30 AM
Last modification	10/01/2015 02:20 AM
Published Date	09/21/2012
Products	• Servers and Clusters • SGI Origin/Onyx • Origin/Onyx Server • Software • Legacy Software • Operating Systems • IRIX • Workstations • SGI Tezro • O2 • Octane
Categories	• Knowledgebase • Technical Solution